

Bay Club Tower 2

The Badger 380 BTU flow meter measuring primary loop flow has been providing incorrect measurements since 4/03/2017. The flow after the meter malfunctioned is constant at 0 gpm. To allow for heat recovery to be calculated, flow has been stipulated to 77.87 gpm, which is the average flow from 3/28/2017 to 4/2/2017.



