The Veris power meter at Bay Club Tower 1 is measuring half the expected generation given system fuel use. The incorrect measurements started on 6/12/2017, resulting in considerably lower calculated electrical efficiencies at approximately 13% HHV.

